SENSI
Gestanon



Calibration:
3 sec
CAL 0
xxxg
Load
xxxg
xxxg
1. Switch the scale on. Press key without releasing for 3 seconds.
2. The display will show "CAL" → "CAL 0" "Load" ↔ " **/**g ". Load **/**g weight on the platform.
3. Display will show 100.00g/50.00g The calibration is completed.
5.09

EK5055 Max:5kg d=1g
UNIT

0.089
CAMRY