

# **ANALISA KERUNTUHAN BENDUNGAN KUNINGAN DENGAN MENGGUNAKAN PROGRAM ZHONG XING HY21**

**Yufintra Prasetya Sasongko<sup>1</sup>, Pitojo Tri Juwono<sup>2</sup>**

<sup>1</sup>Mahasiswa Program Sarjana Teknik Pengairan Universitas Brawijaya

<sup>2</sup>Dosen Teknik Pengairan Fakultas Teknik Universitas Brawijaya

Jurusan Teknik Pengairan Fakultas Teknik Universitas Brawijaya

Jalan Mayjen Haryono 167 Malang 65145 -Telp (0341) 567886

Email: yufintra26@gmail.com

**ABSTRAK:** Bendungan Kuningan terletak di Dusun Cileuveung, Desa Randusari, Kecamatan Cibeureum, Kabupaten Kuningan Provinsi Jawa Barat. Keruntuhan Bendungan Kuningan dapat terjadi dikarenakan *overtopping* dan *piping*. Dari simulasi yang dilakukan dengan program *Zhong Xing HY21*, keruntuhan akibat *piping* atas kondisi muka air banjir pada Bendungan Kuningan yang mengakibatkan dampak paling besar dengan puncak debit *QInflow* 893,008 m<sup>3</sup>/det dan luas genangan 35,696 Km<sup>2</sup> dengan 32 desa di bagian hilir Bendungan Kuningan yang terkena dampak akibat keruntuhan Bendungan Kuningan. Bendungan Kuningan termasuk dalam klasifikasi bendungan dengan bahaya tingkat 4 yaitu bahaya sangat tinggi dengan total debit outflow yang keluar akibat keruntuhan Bendungan Kuningan yaitu 55570.2727 m<sup>2</sup>/det

**Kata Kunci:** *Zhong Xing HY21, Piping, Overtopping, Bendungan*

**ABSTRACT:** *The Kuningan Dam is located in Cileueung Hamlet, Randusari Village, Cibeureum District, Kuningan Regency, West Java Province. Kuningan Dambreak can occur due to overtopping and piping. The simulation carried out by the Zhong Xing HY21 program, the dambreak due to piping on the flood water level conditions in the Kuningan Dam has the biggest impact with the peak flow QInflow 893,008 m<sup>3</sup>/sec and the inundation area is 35,696 km<sup>2</sup> with 32 villages downstream of the Kuningan Dam affected the impact of the Kuningan dambreak. Kuningan Dam is included in the classification of dam with level 4 hazard, namely very high hazards with total outflow discharge resulting from the break of the Kuningan Dam, which is 55570.2727 m<sup>2</sup>/sec.*

**Keywords :** *Zhong Xing HY21, Piping, Overtopping, Dam*